BOSSIER CITY, LA - BC21 PRIORITY AREA REHAB RECOMMENDATIONS





LEGEND

BC21 Priority Rehab Manholes

- Cementitious lining
- Seal manhole joints, cracks, and holes
- No rehab

BC21 Priority Rehab Pipes

► No rehabilitation

Cured-in-place liner

Dig and replace

Point repair

300 600 900 1,200 Feet